Blue Ember Heating & Air

Licensed mechanical contractor · Lic. #H-00000 · EPA 608 certified techs

915 Kiln Ave
Fernridge, SC 29600
(864) 555-0119 · service@blueember.example

INVOICE

No. **INV-3318**
Date August 12, 2026
Terms Due on completion

BILL TO

Lorraine Pike
3302 Sweetgum Ct
Fernridge, SC 29600
(864) 555-0163

System: 3-ton split heat pump, R-410A, installed 2014
Outdoor unit: Model HP36-14S · Serial 1405-27731 (sample)

No-cooling call — failed run capacitor and pitted contactor

DESCRIPTION	QTY	UNIT	RATE	AMOUNT
Diagnostic service call Weekday visit, includes full system check	1	visit	$129.00	$129.00
Dual run capacitor, 45/5 µF, 440 V Replaced — old part measured far below its rating	1	ea	$189.00	$189.00
Contactor, 2-pole, 30 A Replaced — contacts pitted	1	ea	$165.00	$165.00
Refrigerant R-410A Added to reach the manufacturer's charge — see leak note below	2	lb	$95.00	$190.00
Repair labor	1.5	hr	$110.00	$165.00
Comfort Club member discount (15% off parts, refrigerant excluded)	1	ea	−$53.10	−$53.10

Subtotal	$784.90
Sales tax (example rate 7%)	$34.36
Total	**$819.26**
Balance due	**$819.26**

READINGS AFTER REPAIR

Reading	Value
Outdoor temperature	91°F
Return air / supply air	76°F / 57°F
New capacitor, measured	45.2 / 5.0 µF
Subcooling / superheat	10°F / 9°F — within the maker's chart

NOTES AND TERMS

- The system was low on refrigerant, which means a leak somewhere. We recommend a leak search; estimate EST-1203 is sent separately.
- Warranty: parts we supplied, 1 year; labor on this repair, 90 days.
- Payment due on completion.

How to pay: Card, bank transfer (ACH) through the pay link, or check.

Customer signature — work completed

Date