Copperdial Appliance Repair

Refrigeration · Laundry · Cooking

38 Tinker Ave
Hollis Grove, PA 19000
(215) 555-0149 · service@copperdial.example

INVOICE

No. **INV-0938**
Date November 13, 2026
Terms Due on completion

BILL TO

Irene Kowalski
2114 Chestnut Row
Hollis Grove, PA 19000
(215) 555-0173 · i.kowalski@example.com

Appliance: Side-by-side refrigerator · Model RS-2650X · Serial 26K-0417 (sample)

Refrigerator not cooling — evaporator fan motor

DESCRIPTION	QTY	UNIT	RATE	AMOUNT
Diagnostic fee	1	ea	$95.00	$95.00
Diagnostic credit — repair approved	1	ea	−$95.00	−$95.00
Evaporator fan motor, OEM part Part # EF-1140 (sample)	1	ea	$118.00	$118.00
Repair labor — evaporator fan motor replacement	1	job	$165.00	$165.00
Defrost system check Heater and thermostat tested OK	1	ea	$0.00	$0.00

Subtotal	$283.00
Sales tax (example rate 6%)	$7.08
Total	**$290.08**
Balance due	**$290.08**

NOTES AND TERMS

- Customer approved the repair quote on site before work began.
- Warranty: 90 days on parts and labor for this repair.
- Also found Nov 13: the door gasket is worn at the bottom corner. Not replaced at the customer's request; quote available.

How to pay: Card or bank transfer (ACH) through the pay link.

Customer signature — work completed

Date

Sample invoice — every name, address and price on it is fictional, and the tax is an example: which lines are taxable depends on your state.