Mudhawk Drywall & Texture

Hang · Finish · Texture · Repairs

88 Gypsum Way
Saguaro Flats, AZ 85300
(602) 555-0170 · office@mudhawk.example

INVOICE

No. **INV-0566**
Date November 12, 2026
Terms Net 15 · November 27, 2026

BILL TO

Arturo Villalobos
1715 Mesquite Trl
Saguaro Flats, AZ 85300
(602) 555-0112 · a.villalobos@example.com

Insurance claim: HO-2026-55120

Ceiling and wall repair after a plumbing leak — hall bath and hallway

DESCRIPTION	QTY	UNIT	RATE	AMOUNT
Remove and dispose of water-damaged drywall 96 sq ft of wall and 64 sq ft of ceiling	160	sq ft	$1.85	$296.00
Moisture check of framing before close-up Readings logged; framing dry	1	ea	$0.00	$0.00
Hang 1/2-in. drywall, walls	3	sheet	$52.00	$156.00
Hang 5/8-in. ceiling board Matches the existing ceiling board	2	sheet	$64.00	$128.00
Tape and finish walls to Level 4	96	sq ft	$1.95	$187.20
Tape and finish ceiling to Level 3 (under texture)	64	sq ft	$1.75	$112.00
Match existing knockdown ceiling texture	64	sq ft	$2.40	$153.60
Metal corner bead, replaced	16	lin ft	$3.50	$56.00
Prime repaired areas	160	sq ft	$0.55	$88.00

Subtotal	$1,176.80
Total	**$1,176.80**
Balance due	**$1,176.80**

NOTES AND TERMS

- Finish levels per the Gypsum Association's GA-214: Level 4 on the walls (ready for flat or eggshell paint) and Level 3 on the ceiling under the knockdown texture. Paint by others.
- Texture is matched as closely as possible; new texture on an older ceiling can look slightly different under raking light.
- Billed to the homeowner; the claim number is included for your insurer.

How to pay: Card or bank transfer (ACH) through the pay link, or check.

Customer signature — work completed

Date